

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14522 Main Street: CARONIA_ST Cross Street: REID_AV Location: SW

ADA ID: CF3ACCA088D5 Ramp Type: Combination2Diag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
StopSign
Stop Condition-Street 1
REID AV
Street 2 Name
StopSign
Stop Condition-Street 2
CARONIA ST

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3, R304.3.2

Not Found, R304.5.1, R304.5.3, N/A
R304.3.2 N/A
N/A
N/A
N/A
Total Cost: \$ 3200.00 N/A

Comp	liance Description	Data		iance Description	
N/A	Ramp Length LT (in)	62.0	N/A	Ramp Length RT (in) N/A
Yes	Ramp Width LT (in)	61.0	N/A	Ramp Width RT (ii	n) N/A
No	Ramp Slope LT (%)	9.1	N/A	Ramp Slope RT (%	%) N/A
Yes	Ramp XSlope LT (%)	1.0	N/A	Ramp XSlope RT	(%) N/A
N/A	Ramp Length (in)	61.0	Yes	Ramp Slope (%)	4.6
No	Ramp Width (in)	33.0	No	Ramp XSlope (%)	7.0
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%) N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable	RT? N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%) N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To E		X Walk 2 Direction	To N
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in) N/A
	X Walk 1 Slope (%)	5.9		X Walk 2 Slope (%	0.8
	X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope	(%) 4.6
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWa	k2? N/A
	Road Slope (%)	3.6		Clear Space?	N/A
	Road X Slope (%)	4.8	N/A	Clear Space to XV	Valk (in) N/A
			N/A	Any Obstruction?	N/A
V				Obstruction Type	
					N/A

N/A

Yes

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Curb Slope (%)

N/A

N/A

Good

14.8





