

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 19174 Main Street: RENWICK\_RD Cross Street: SARDIS\_RD Location: NE

ADA ID: CF5B922FDA49 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

**Codes/Mitigation Info/Possible Solution** 



Street 1 Name
SARDIS RD
Stop Condition-Street 2
None
Street 2 Name
N/A
Stop Condition-Street 1
N/A

Possible Solution	
Possible Solutions:	Com
Remove & Replace Entire Ramp.	N/A
•	Yes
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
Not Found, R304.2.2	N/A
	N/A
	N/A
	N/A

Total Cost:



1850.00

Field Measurements/Component Compliance							
Comp	liance Description	Data	Comp	liance	Description	Data	
N/A	Ramp Length (in)	60.0	No	Ram	Slope (%)	9.7	
Yes	Ramp Width (in)	48.0	Yes	Ram	XSlope (%)	1.4	
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A	
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A	
	X Walk 1 Direction	To S		X Wa	lk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	1.6		X Wa	lk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	0.0		X Wa	lk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A	
	Obstruction Type			Storn	n Grate/Utility Type		
		N/A				N/A	
			Yes	Surfa	ce Condition? (G/P)	Good	
100							