

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 6835 Main Street: RUMSON_CT Cross Street: WINGDALE_DR Location: N **Overall Compliance: No** ADA ID: CF5DC65155A9 Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 8.75

Codes/Mitigation Info/Possible Solution



RUMSON CT Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:	9			
Remove & Replace Entire Ramp.				
·	ı			
	١			
	ı			
	ı			
	ı			
Surveyor Notes:	ı			
N/A	ı			
	ı			
	ı			
	ı			
PROW/ADA:	ı			
Not Found, R304.5.1	١			
	ı			
	ı			
	ı			

Total Cost: 1850.00

Field Measurements/Component Compliance							
Comp	liance Description	Data	Comp	liance Description	Data		
N/A	Ramp Length (in)	49.0	Yes	Ramp Slope (%)	6.1		
No	Ramp Width (in)	41.0	Yes	Ramp XSlope (%)	1.7		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		





