

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

8.8

4.5

N/A

Intersection ID: 10029225 Main Street: JOHNSTON_RD Cross Street: N/A Location: W

ADA ID: CF999BF3211A Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75

P. Control of the state of the

Codes/Mitigation Info/Possible Solution

sible SolutionField Measurements/Component Complianceible Solutions:ComplianceDescriptionDataComplianceDescription

Possible Solutions:						
Remove & Replace Entire Ramp.						
Surveyor Notes:						
N/A						
PROW/ADA:						
R304.2.2, R304.5.3						

COIIII	onance Description	Data	COIII	manice	Description	
N/A	Ramp Length (in)	58.0	No	Ramp Slope (%)		
Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)		
N/A	Flare Type LT	N/A	N/A	Flare Type RT		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)		
N/A	Flare Traversable LT?	N/A	N/A	N/A Flare Traversable		
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter	Slope (%)	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?		
	X Walk 1 Direction	To NW		X Wal	k 2 Direction	
N/A	X Walk 1 Width (in)	N/A	N/A	X Wal	k 2 Width (in)	
	X Walk 1 Slope (%)	2.3		X Wal	k 2 Slope (%)	
	X Walk 1 X Slope (%)	1.6		X Wal	k 2 X Slope (%)	

Ramp inside XWalk1?

Road Slope (%)

Street 1 Name	ENTRANCE
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Total Cost: \$ 1850.00

Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A Any Obstructions? N/A Storm Grate/Utility Hazard? N/A N/A N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good

N/A N/A

N/A

N/A

Ramp inside XWalk2?

Clear Space?







N/A