


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 45778	Main Street: CARVER FALLS RD	Cross Street: WINDING RIVER DR	Location: SE
ADA ID: CFEBF8F2CF15	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 21.25	

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance			
 <p>Street 1 Name WINDING RIVER DR</p> <p>Stop Condition-Street 2 StopSign</p> <p>Street 2 Name CARVER FALLS RD</p> <p>Stop Condition-Street 1 None</p>	<p>Possible Solutions:</p> <p>Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.</p> <p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.5.1, R304.5.3</p>	<p>Total Cost:</p> <p>\$ 3200.00</p>			
			Compliance	Description	Data
			Compliance	Description	Data
			N/A	Ramp Length (in)	73.0
			No	Ramp Width (in)	44.5
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To N
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	0.2
				X Walk 1 X Slope (%)	4.7
			N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	4.4
				Road X Slope (%)	3.6
			N/A	Any Obstructions?	N/A
				Obstruction Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good

