

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11977Main Street: CHARETTE_CTCross Street: PLOTT_RDLocation:NEADA ID: D054177EF1BCRamp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 8.75

Codes/Mitigation Info/Possible Solution



Street 1 Name
CHARETTE CT
Stop Condition-Street 2
StopSign
Street 2 Name
N/A
Stop Condition-Street 1
N/A

| 71 CSSIDIC COIGITOTI | |
|-------------------------------|----------|
| Possible Solutions: | <u>c</u> |
| Remove & Replace Entire Ramp. | N |
| · | N |
| | N. |
| | N |
| | N |
| | N |
| Surveyor Notes: | N |
| N/A | N |
| | N |
| | N |
| | N |
| PROW/ADA: | N |
| Not Found, R304.5.1 | N. |
| Ý | N |
| | N |
| | N |



Total Cost:



1850.00

| Field Measurements/Component Compliance | | | | | | |
|---|-----------------------|-------|------|-----------------------------|------|--|
| Compl | iance Description | Data | Comp | liance Description | Data | |
| N/A | Ramp Length (in) | 25.0 | Yes | Ramp Slope (%) | 8.3 | |
| No | Ramp Width (in) | 44.0 | Yes | Ramp XSlope (%) | 1.7 | |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| N/A | Shared Landing? | N/A | | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A | |
| | X Walk 1 Direction | To SW | | X Walk 2 Direction | N/A | |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | |
| | X Walk 1 Slope (%) | 4.0 | | X Walk 2 Slope (%) | N/A | |
| | X Walk 1 X Slope (%) | 4.5 | | X Walk 2 X Slope (%) | N/A | |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | |
| | Road Slope (%) | N/A | N/A | Clear Space? | N/A | |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A | |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | |
| | Obstruction Type | | | Storm Grate/Utility Type | | |
| | | N/A | | | N/A | |
| | | | Yes | Surface Condition? (G/P) | Good | |
| | | | | | | |

