

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4995 Main Street: MASON_DR Cross Street: WILKINS_TERRACE_DR Location: SW

ADA ID: D072C3BA28BC Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 58.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name	WILKINS TERRACE DR
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

FOSSIBLE SOLUTION		
Possible Solutions:		
Remove & Replace Entire Ramp.		
	ı	
Surveyor Notes:		
•		
N/A		
PROW/ADA:		
Not Found, R304.5.1, R304.2.2,	I	
R304.5.3		

Total Cost:			\$ •	1850.	00

Field Measurements/Component Compilance							
Comp	liance Description	Data	Comp	liance Description	Data		
N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	20.0		
No	Ramp Width (in)	42.0	No	Ramp XSlope (%)	9.4		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To NW		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	3.7		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	8.7		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		





