

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 32290	Main Stre	et: CLEMENTINE_CT	Cros	Cross Street: STEWARTS_BEND_LN				Location:	NE
ADA ID: D0B1FE7CCC9E	Ramp Typ	Ramp Type: Combination1Diag			Initial Pass/Fail: Fail Overall Complian			ice: No Severity Score:	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data Compliance Description			Data
		Remove & Replace C	urb Ramp With	N/A	Ramp Length LT (in)	56.0	N/A	Ramp Length RT (in)	72.0
		Two New Directional R Equivalent.		No	Ramp Width LT (in)	47.0	No	Ramp Width RT (in)	46.0
			-	Yes	Ramp Slope LT (%)	8.1	Yes	Ramp Slope RT (%)	4.6
				No	Ramp XSlope LT (%)	2.6	No	Ramp XSlope RT (%)	2.2
	Sale Of			N/A	Ramp Length (in)	46.0	Yes	Ramp Slope (%)	7.4
				No	Ramp Width (in)	43.0	No	Ramp XSlope (%)	5.6
		Surveyor Notes:		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
a A		RT RP < 5%		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
CLEMENT	NIL OT			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
the				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		PROW/ADA:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		Not Found, R304.5.1, R304.5.1,		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		R304.5.3		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Dec.	- E.) CO			N/A	Shared Landing?	N/A			
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	None			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1 STE	WARTS BEND LN			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
Street 2 Name	StopSign				X Walk 1 Direction	To W		X Walk 2 Direction	To S
Stop Condition-Street 2	CLEMENTINE CT	EMENTINE CT			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	3.8
					X Walk 1 X Slope (%)	4.3		X Walk 2 X Slope (%)	2.6
		Total Cost:	\$ 3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
					Road Slope (%)	4.9		Clear Space?	N/A
					Road X Slope (%)	1.1	N/A	Clear Space to XWalk (in)	N/A
					And a state of the second		N/A	Any Obstruction?	N/A
								Obstruction Type	
					1				N/A
-					207		N/A	Storm Grate/Utility Hazard? Storm Grate/Utility Type	N/A

 Yes
 Surface Condition? (G/P)
 Good Curb Slope (%)





