

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23903	Main Street: CARMEL RD			Cross	Street:	PEPPERIDGE_DR	Location:	NW		
ADA ID: D0D7C37B6580	Ramp Type: Perp				Initial Pass/Fail: Fail Overall Compliance: No					
· · · ·			Intia	1 433/1 6			10.75			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance Compliance Description Data						
Carl and the Carl and the		Possible Solutions:			Compliance Description			Data Compliance Description		
		Remove & Replace Entir	e Ram	р.	N/A	Ramp Length (in)	56.0	No	Ramp Slope (%)	9.4
					Yes	Ramp Width (in)	49.0	No	Ramp XSlope (%)	2.3
Company Distance					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
Para Calina					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
and the second s	R R	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
PEPPERIDOR		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
DR CHE DR					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	4				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
the second second					N/A	Shared Landing?	N/A			
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.2.2, R3	04.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			041010		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
						X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	PEPPERIDGE DR	-				X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
	0/6					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A N/A
		Total Cost:	¢	1850.00	11/2	Obstruction Type	13/A		Storm Grate/Utility Type	17/5
			φ	1000.00		Obstruction Type	N1/A		Storm Grate/Otimity Type	NI/A
							N/A			N/A

s Surface Condition? (G/P)

Good

