


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10020495		Main Street: BARCLAY_DOWNS_DR		Cross Street: N/A		Location:		SW			
ADA ID: D0E7B55D44EB		Ramp Type: Directional2		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 1.25			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance							
<div></div> <div>Street 1 NameENTRANCE</div> <div>Stop Condition-Street 1StopSign</div> <div>Street 2 NameN/A</div> <div>Stop Condition-Street 2N/A</div>				Possible Solutions:		Compliance		Description		Data	
				Remove & Replace Entire Ramp.		N/A		Ramp Length (in)		48.5	
Surveyor Notes:				N/A		Yes		Ramp Width (in)		52.0	
						Yes		Ramp Slope (%)		3.1	
PROW/ADA:				R304.5.3		No		Ramp XSlope (%)		2.6	
						N/A		Flare Type LT		N/A	
						N/A		Flare Slope LT (%)		N/A	
						N/A		Flare Traversable LT?		N/A	
						N/A		Landing Length (in)		0.0	
						N/A		Landing Width (in)		0.0	
						N/A		Landing Slope (%)		0.0	
						N/A		Landing X Slope (%)		0.0	
						N/A		Landing Curb? (Y/N)		N/A	
						N/A		Shared Landing?		N/A	
						N/A		Gutter Ponding?		0.0	
						N/A		Gutter Lip Ht (in)		0.0	
						N/A		Painted X Walk1?		No	
								X Walk 1 Direction		To N	
								X Walk 1 Width (in)		N/A	
								X Walk 1 Slope (%)		0.4	
								X Walk 1 X Slope (%)		1.3	
						N/A		Ramp inside XWalk1?		N/A	
						N/A		Any Obstructions?		N/A	
								Obstruction Type		Yes	
								Surface Condition? (G/P)		Good	
						N/A		Curb Slope (%)		N/A	

