

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

40.0

48.0

6.6

2.2

8.4

0.2

N/A

N/A

N/A

N/A

N/A

N/A

16.1

Intersection ID: 9055 Main Street: DOGWOOD_AV Cross Street: ENNIS_AV Location: NW
ADA ID: D1E9983F3AE1 Ramp Type: Combination1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 22.5

Compliance Description

N/A

No

Yes

Yes

N/A

Yes

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A N/A

N/A

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

No

No

Yes

N/A

N/A

N/A

N/A

N/A

N/A N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

Curb Slope (%)

Flare Traversable RT?

Flare Type RT

Ramp XSlope RT (%)

Data

39.5

44.5

5.2

0.3

29.0

48.0

N/A

N/A

N/A

N/A

N/A



Street 1 Name
StopSign
Stop Condition-Street 1
ENNIS AV
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3



Total Cost:



1800.00

	Landing Glope (70)	11/7	11//	DVVO Length (III)	11/7
	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	Shared Landing?	N/A			
	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.6		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	1.7		X Walk 2 X Slope (%)	N/A
	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
	6 4 3		N/A	Any Obstruction?	N/A
	100000			Obstruction Type	
					N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	
74 -					N/A
-	- 1		Yes	Surface Condition? (G/P)	Good
5554017					