


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                        |                             |                              |                        |
|------------------------|-----------------------------|------------------------------|------------------------|
| Intersection ID: 23300 | Main Street: SHARON_RD_WEST | Cross Street: SHARONBROOK_DR | Location: NE           |
| ADA ID: D22955505FE3   | Ramp Type: Perp             | Initial Pass/Fail: Fail      | Overall Compliance: No |
|                        |                             |                              | Severity Score: 13.75  |

| Codes/Mitigation Info/Possible Solution   |  |                   | Field Measurements/Component Compliance |                             |             |
|---|--|-------------------|---|-----------------------------|-------------|
|                       | Possible Solutions:                      |                   | <b>Compliance</b>                       | <b>Description</b>          | <b>Data</b> |
|   | <b>Remove &amp; Replace Entire Ramp.</b> |                   | <b>No</b>                               | Ramp Length (in)            | <b>61.0</b> |
|   |  |                   | <b>Yes</b>                              | Ramp Width (in)             | <b>48.0</b> |
|   |  |                   | <b>N/A</b>                              | Flare Type LT               | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | Flare Slope LT (%)          | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | Flare Traversable LT?       | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | Landing Length (in)         | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | Landing Width (in)          | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | Landing Slope (%)           | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | Landing X Slope (%)         | <b>N/A</b>  |
| <p>Surveyor Notes:</p> <p><b>N/A</b></p> <p>PROW/ADA:</p> <p><b>Not Found, R304.2.2, R304.5.3</b></p> |  |                   | <b>N/A</b>                              | Flare Type RT               | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | Flare Slope RT (%)          | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | Flare Traversable RT?       | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | DWS Provided?               | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | DWS Contrast?               | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | DWS Length (in)             | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | DWS Full Width?             | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | DWS Offset (in)             | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | Shared Landing?             | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | Gutter Ponding?             | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | Gutter Lip Ht (in)          | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | Painted X Walk1?            | <b>No</b>   |
|   |  |                   |   | X Walk 1 Direction          | <b>To E</b> |
|   |  |                   | <b>N/A</b>                              | X Walk 1 Width (in)         | <b>N/A</b>  |
|   |  |                   |   | X Walk 1 Slope (%)          | <b>2.4</b>  |
|   |  |                   |   | X Walk 1 X Slope (%)        | <b>1.6</b>  |
|   |  |                   | <b>N/A</b>                              | Ramp inside XWalk1?         | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | Road Slope (%)              | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | Road X Slope (%)            | <b>N/A</b>  |
|   |  |                   | <b>N/A</b>                              | Any Obstructions?           | <b>N/A</b>  |
| Total Cost:   |  | <b>\$ 1850.00</b> |   | Obstruction Type            |             |
|   |  |                   | <b>N/A</b>                              | Storm Grate/Utility Hazard? | <b>N/A</b>  |
|   |  |                   |   | Storm Grate/Utility Type    |             |
|   |  |                   | <b>N/A</b>                              |                             | <b>N/A</b>  |
|   |  |                   | <b>Yes</b>                              | Surface Condition? (G/P)    | <b>Good</b> |

