

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

58.0

33.0

9.0

2.2

3.3

1.8

N/A

Good

8.8

Intersection ID: 11331 **Cross Street: MEADOW ROSE LN** Location: Main Street: E W T HARRIS BV NW Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: D2361E94B65D Ramp Type: Combination1 Severity Score: 31.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

No

No

Yes

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Type RT

Ramp XSlope RT (%)

Surface Condition? (G/P)

Curb Slope (%)

Data

52.0

35.0

5.6 No

3.9

27.5

N/A N/A

48.0 Yes

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Type LT

Ramp XSlope LT (%)



YieldSign Street 1 Name MILTON RD Stop Condition-Street 1 Street 2 Name N/A Stop Condition-Street 2 N/A Possible Solutions: Compliance Description Remove & Replace Entire Ramp. N/A No Yes No N/A Yes Surveyor Notes: N/A N/A PROW/ADA: Not Found, R304.5.1, R304.5.3, R304.3.2



Total Cost:



1800.00

N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	112.5		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	2.2		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
	250 616.		N/A	Any Obstruction?	N/A
				Obstruction Type	
	11				N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	
					N/A

Yes