

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | |
|------------------------|------------------------|----------------------------|------------------------|
| Intersection ID: 16207 | Main Street: MONROE_RD | Cross Street: COMMODORE_ST | Location: SE |
| ADA ID: D2407E368E60 | Ramp Type: ParaDiag | Initial Pass/Fail: Fail | Overall Compliance: No |
| | | Severity Score: 22.5 | |

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.1, R304.3.2, R304.5.3

Total Cost: \$ 3200.00

| Compliance | Description | Data | Compliance | Description | Data |
|------------|----------------------|-------|------------|-----------------------------|-------|
| N/A | Ramp Length LT (in) | 55.0 | N/A | Ramp Length RT (in) | 55.0 |
| No | Ramp Width LT (in) | 36.0 | No | Ramp Width RT (in) | 46.0 |
| No | Ramp Slope LT (%) | 9.0 | No | Ramp Slope RT (%) | 9.3 |
| Yes | Ramp XSlope LT (%) | 0.3 | No | Ramp XSlope RT (%) | 2.6 |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| N/A | Shared Landing? | N/A | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | X Walk 1 Direction | To NE | | X Walk 2 Direction | To NW |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 0.5 | | X Walk 2 Slope (%) | 0.5 |
| | X Walk 1 X Slope (%) | 0.2 | | X Walk 2 X Slope (%) | 1.4 |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | 0.4 | N/A | Clear Space? | N/A |
| | Road X Slope (%) | 0.1 | N/A | Clear Space to XWalk (in) | N/A |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | N/A | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |
| | | | N/A | Curb Slope (%) | 1.1 |

Street 1 Name **MONROE RD**
 Stop Condition-Street 1 **None**
 Street 2 Name **COMMODORE ST**
 Stop Condition-Street 2 **StopSign**

