

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9953 Main Street: TRIANGLE_DR **Cross Street: TUCKASEEGEE_RD** Location: W **Overall Compliance: No ADA ID: D28E4E5326CB** Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 35

Codes/Mitigation Info/Possible Solution



Street 1 Name **TUCKASEEGEE RD** Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:	<u>c</u>	
Remove & Replace Entire Ramp.		
·	N	
	N	
	N	
	N	
	N	
Surveyor Notes:	N	
N/A	N	
	N	
	N	
	N	
PROW/ADA:	N	
Not Found, R304.5.1, R304.2.2,	N	
R304.5.3	N	
	N	

Total Cost:	\$	1850.00

Field Measurements/Component Compliance								
Comp	liance Description	Data	Comp	liance Description	Data			
N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	13.0			
No	Ramp Width (in)	42.5	No	Ramp XSlope (%)	2.7			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A			
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A			
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A			
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A			
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A			
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A			
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A			
	X Walk 1 Direction	To E		X Walk 2 Direction	N/A			
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A			
	X Walk 1 Slope (%)	2.3		X Walk 2 Slope (%)	N/A			
	X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	N/A			
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A			
	Road Slope (%)	N/A	N/A	Clear Space?	N/A			
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A			
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A			
	Obstruction Type			Storm Grate/Utility Type				
		N/A			N/A			
			Yes	Surface Condition? (G/P)	Good			
	Jan State Control							





