cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · · · · · · · · · · · · · · · · ·									
Intersection ID: 44207	Main Str	Main Street: MOCKERNUT_DR			TARTARIAN_CT	Location:	SW		
ADA ID: D291D87790EB	Ramp Ty	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				22.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
	5	Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	49.5	No	Ramp Slope (%)	10.2
		Two New Directional Ramps or		No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	3.1
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
TRATATION				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		PROW/ADA:		N/A	Shared Landing?	N/A		2110 011001 (11)	1071
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
1 Juli Fre		Not Found, R304.5.1, R304.2.2, R304.5.3	I	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	1004.3.5		17/4	X Walk 1 Direction	To E		X Walk 2 Direction	To N	
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
			N/A			N/A			
Street 1 Name	MOCKERNUT DR				X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	5.0
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	4.6		X Walk 2 X Slope (%)	2.6
Street 2 Name	TARTARIAN CT			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	1.5		Clear Space?	N/A
					Road X Slope (%)	2.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

