


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 45644	Main Street: W_5TH_ST	Cross Street: W_6TH_ST	Location:	E
ADA ID: D2A5DD54F328	Ramp Type: BlendTrans1	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 7.5

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance							
	Possible Solutions:		Compliance			Description			Data	
	Remove & Replace Landing. Grind Gutter Lip.		N/A	Ramp Length (in)	71.0	Yes	BlendTrans Slope (%)	4.7		
			Yes	Ramp Width (in)	48.0	Yes	BlendTrans XSlope (%)	1.5		
			N/A	Flare Type LT	None	N/A	Flare Type RT	Sloped		
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	4.1		
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	No		
			Yes	Landing Length (in)	85.0	Yes	DWS Provided?	Yes		
			Yes	Landing Width (in)	71.0	Yes	DWS Contrast?	Yes		
			No	Landing Slope (%)	2.9	Yes	DWS Length (in)	24.0		
			No	Landing X Slope (%)	3.8	Yes	DWS Full Width?	Yes		
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.2.2-Perp, R304.3.2-Para, R304.5.3, R302.7.2</p>			N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	2.0		
			N/A	Shared Landing?	No					
			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.8		
			No	Gutter Lip Ht (in)	0.5	Yes	Gutter X Slope (%)	1.0		
			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A		
				X Walk 1 Direction	To SE		X Walk 2 Direction	N/A		
				X Walk 1 Width (in)	111.0		X Walk 2 Width (in)	N/A		
				X Walk 1 Slope (%)	3.2		X Walk 2 Slope (%)	N/A		
				X Walk 1 X Slope (%)	3.7		X Walk 2 X Slope (%)	N/A		
			Yes	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A		
<p>Total Cost:</p> <p>\$ 700.00</p>				Road Slope (%)	3.7		Clear Space?	Yes		
				Road X Slope (%)	3.2	N/A	Clear Space to XWalk (in)	N/A		
			Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No		
				Obstruction Type			Storm Grate/Utility Type			
						N/A		N/A		
						Yes	Surface Condition? (G/P)	Good		
						Yes	Curb Slope (%)	3.7		

