

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Main Street: LAUDER\_CT Intersection ID: 10030174 Cross Street: N/A Location: NE **Overall Compliance: No** ADA ID: D2C4740D07E9 Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 21.25

Codes/Mitigation Info/Possible Solution



SA SERVICE AND REAL PROPERTY OF THE PERSON NAMED IN COLUMN 2 AND ADDRESS OF THE PERSON NAMED IN COLUMN 2 AND A	The second secon
Street 1 Name	LAUDER CT
Stop Condition-Street 2	None
Street 2 Name	N/A
Ston Condition-Street 1	N/A

Possible Solution	
Possible Solutions:	Co
Remove & Replace Entire Ramp.	N/
	No
	N/
	N/
9	N/
	N/
Surveyor Notes:	N/
N/A	N/
	N/
	N/
	N/
PROW/ADA:	N/
Not Found, R304.5.1, R304.5.3	N/
	N/
	N/
	N/



Total Cost:



1850.00

Field Measurements/Component Compliance								
Compl	liance Description	Data	Compl	iance	Description	Data		
N/A	Ramp Length (in)	48.0	Yes	Ramp	Slope (%)	5.5		
No	Ramp Width (in)	45.5	No	Ramp	XSlope (%)	5.8		
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A		
	X Walk 1 Direction	To NW		X Wa	lk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	2.9		X Wa	lk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	4.5		X Wa	lk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm	Grate/Utility Type			
		N/A				N/A		
			Yes	Surfa	ce Condition? (G/P)	Good		