cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		•		-					
Intersection ID: 4716	: 47162 Main Street: SHARON_RD			street:	SHARON_TOWNSHIP	Location:	NW		
ADA ID: D441A4E1A4	A41A Ramp Type: PerpDiag		Initial Pa	Initial Pass/Fail: Fail Overall Compliance: N				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	1.	Possible Solutions:		Compliance Description Data C			Comp	Compliance Description Data	
		Remove & Replace Curb Ramp V	Nith	N/A	Ramp Length (in)	96.0	No	Ramp Slope (%)	8.9
		Two New Directional Ramps or Equivalent.	-	Yes	Ramp Width (in)	60.0	Yes	Ramp XSlope (%)	0.7
138 54				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
1				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	Jally II L.			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Sugar				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Ton	S I	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
AND	<mark>.स</mark> 🖉	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	AN AN ANY	dist.		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
K () K	- Contraction			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
AS ATAS	Dr. I the same			N/A	Shared Landing?	N/A			
	Rom - 1 Part	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	C. 56 8- 1	Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
4. 1 2 3 1 1 1	M. Martin L			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	No
- AL AL	1 States T				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
A Roa Mal	1 Barris Contraction			N/A	X Walk 1 Width (in)	110.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	SHARON TOWNSHIP LN				X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	1.9
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	4.3		X Walk 2 X Slope (%)	1.6
Street 2 Name	SHARON RD			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	Signal				Road Slope (%)	2.1	N/A	Clear Space?	N/A
					Road X Slope (%)	2.0	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
1							I		

Yes Surface Condition? (G/P)

Good

