

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10025398 Main Street: E_ARROWOOD_RD Cross Street: S_OAK_MARKETPLACE_DR Location: SE

ADA ID: D4C730E0DB82 Ramp Type: Directional1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



| Street 1 Name | E ARROWOOD RD |
|-------------------------|---------------|
| Stop Condition-Street 1 | None |
| Street 2 Name | N/A |
| Stop Condition-Street 2 | N/A |

| Possible Solutions: | С | | |
|-------------------------------|---|--|--|
| Remove & Replace Entire Ramp. | | | |
| | Y | | |
| | Y | | |
| | N | | |
| | N | | |
| | N | | |
| Surveyor Notes: | N | | |
| N/A | N | | |
| | N | | |
| | N | | |
| | N | | |
| PROW/ADA: | N | | |
| R304.5.3 | N | | |
| | N | | |
| | N | | |
| | N | | |
| | | | |
| | | | |
| | | | |

| Total Cost: | \$ 1600.00 |
|-------------|---------------|

| Field Measurements/Component Compliance | | | | | | | | |
|---|-----------------------|------|------|-----------------------------|------|--|--|--|
| Comp | liance Description | Data | Comp | liance Description | Data | | | |
| N/A | Ramp Length (in) | 80.5 | N/A | Grade Break? | N/A | | | |
| Yes | Ramp Width (in) | 94.0 | N/A | Grade Break Slope (%) | 0.0 | | | |
| Yes | Ramp Slope (%) | 7.4 | N/A | Grade Break XSlope (%) | 0.0 | | | |
| No | Ramp XSlope (%) | 8.0 | | | | | | |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | | | |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | 0.0 | | | |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | | | |
| N/A | Landing Length (in) | 0.0 | N/A | DWS Provided? | N/A | | | |
| N/A | Landing Width (in) | 0.0 | N/A | DWS Contrast? | N/A | | | |
| N/A | Landing Slope (%) | 0.0 | N/A | DWS Length (in) | N/A | | | |
| N/A | Landing X Slope (%) | 0.0 | N/A | DWS Full Width? | N/A | | | |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset LT (in) | N/A | | | |
| N/A | Shared Landing? | N/A | N/A | DWS Offset RT (in) | N/A | | | |
| N/A | Gutter Ponding? | 0.0 | N/A | Gutter Slope (%) | N/A | | | |
| N/A | Gutter Lip Ht (in) | 0.0 | N/A | Gutter X Slope (%) | N/A | | | |
| N/A | Painted X Walk1? | No | | Road Slope (%) | 1.0 | | | |
| | X Walk 1 Direction | To N | | Road X Slope (%) | 6.8 | | | |
| | X Walk 1 Width (in) | N/A | | Clear Space? | N/A | | | |
| | X Walk 1 Slope (%) | 1.6 | N/A | Clear Space to XWalk (in) | N/A | | | |
| | X Walk 1 X Slope (%) | 6.8 | N/A | Storm Grate/Utility Hazard? | N/A | | | |
| N/A | Ramp inside XWalk1? | N/A | | Storm Grate/Utility Type | | | | |
| N/A | Any Obstructions? | N/A | | | N/A | | | |
| | Obstruction Type | | Yes | Surface Condition? (G/P) | Good | | | |
| | | N/A | N/A | Curb Slope (%) | 3.4 | | | |
| | | | | | | | | |





