

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 7467	Main Str	Main Street: STONEHURST_DR				Cross Street: TOMAHAWK_LN				N/A	
ADA ID: D4C9A3BFA3ED	Ramp Ty	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Cor			nce: N	o Severity Score:	46.25	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	A. 19 19.	Possible Solutions:			Compliance Description			Data Compliance Description			
	The second	Remove & Replace Entire	e Ram	D.	N/A	Ramp Length (in)	47.0	No	Ramp Slope (%)	11.3	
	~1.13			•	No	Ramp Width (in)	45.0	No	Ramp XSlope (%)	7.4	
13	S FR				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
The total and the	A CO				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
0					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	1000	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
THER		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
TOUTERUS	A BANK AND				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
Sher	and see				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
6. 6	A TH				N/A	Shared Landing?	N/A				
	and the	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	the the	R304.5.1, R304.2.2, R304	.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	and the	·····,····,·····,·····			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	Real and					X Walk 1 Direction	To S		X Walk 2 Direction	N/A	
	1 stiels				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name STO	NEHURST DR	_				X Walk 1 Slope (%)	6.3		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	7.0		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	7.0	N/A	Clear Space?	N/A	
						Road X Slope (%)	6.3	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	

Yes Surface Condition? (G/P)

Good

