


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 48408	Main Street: ERNIE_DR	Cross Street: BRYN_ATHYN_CT	Location:	N
ADA ID: D4F4764DBE68	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 7.5

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance							
	Possible Solutions:		<b>Compliance</b>			<b>Description</b>			<b>Data</b>	
	<b>Remove &amp; Replace Entire Ramp.</b>		<b>N/A</b>		Ramp Length (in)	<b>47.5</b>	<b>Yes</b>	Ramp Slope (%)	<b>6.7</b>	
	<b>Remove &amp; Replace Gutter.</b>		<b>Yes</b>		Ramp Width (in)	<b>48.0</b>	<b>Yes</b>	Ramp XSlope (%)	<b>0.8</b>	
			<b>N/A</b>		Flare Type LT	<b>Sloped</b>	<b>N/A</b>	Flare Type RT	<b>N/A</b>	
			<b>N/A</b>		Flare Slope LT (%)	<b>5.2</b>	<b>N/A</b>	Flare Slope RT (%)	<b>6.3</b>	
			<b>N/A</b>		Flare Traversable LT?	<b>No</b>	<b>N/A</b>	Flare Traversable RT?	<b>No</b>	
			<b>Yes</b>		Landing Length (in)	<b>48.0</b>	<b>Yes</b>	DWS Provided?	<b>Yes</b>	
			<b>Yes</b>		Landing Width (in)	<b>48.0</b>	<b>Yes</b>	DWS Contrast?	<b>Yes</b>	
			<b>No</b>		Landing Slope (%)	<b>2.5</b>	<b>Yes</b>	DWS Length (in)	<b>24.0</b>	
			<b>Yes</b>		Landing X Slope (%)	<b>1.4</b>	<b>No</b>	DWS Full Width?	<b>No</b>	
Surveyor Notes:	<b>N/A</b>		<b>N/A</b>		Landing Curb? (Y/N)	<b>No</b>	<b>Yes</b>	DWS Offset (in)	<b>1.5</b>	
			<b>N/A</b>		Shared Landing?	<b>No</b>				
			<b>Yes</b>		Gutter Ponding?	<b>No</b>	<b>No</b>	Gutter Slope (%)	<b>6.8</b>	
			<b>Yes</b>		Gutter Lip Ht (in)	<b>0.0</b>	<b>Yes</b>	Gutter X Slope (%)	<b>0.2</b>	
			<b>N/A</b>		Painted X Walk1?	<b>No</b>	<b>N/A</b>	Painted X Walk2?	<b>N/A</b>	
					X Walk 1 Direction	<b>To E</b>		X Walk 2 Direction	<b>N/A</b>	
			<b>N/A</b>		X Walk 1 Width (in)	<b>N/A</b>	<b>N/A</b>	X Walk 2 Width (in)	<b>N/A</b>	
					X Walk 1 Slope (%)	<b>2.9</b>		X Walk 2 Slope (%)	<b>N/A</b>	
					X Walk 1 X Slope (%)	<b>0.2</b>		X Walk 2 X Slope (%)	<b>N/A</b>	
			<b>N/A</b>		Ramp inside XWalk1?	<b>N/A</b>	<b>N/A</b>	Ramp inside XWalk2?	<b>N/A</b>	
PROW/ADA:	<b>Not Found, R304.2.2-Perp, R304.3.2-Para, R305.1.4, R304.5.4</b>				Road Slope (%)	<b>N/A</b>	<b>N/A</b>	Clear Space?	<b>Yes</b>	
					Road X Slope (%)	<b>N/A</b>	<b>N/A</b>	Clear Space to XWalk (in)	<b>N/A</b>	
			<b>Yes</b>		Any Obstructions?	<b>No</b>	<b>Yes</b>	Storm Grate/Utility Hazard?	<b>No</b>	
					Obstruction Type			Storm Grate/Utility Type		
							<b>N/A</b>		<b>N/A</b>	
							<b>Yes</b>	Surface Condition? (G/P)	<b>Good</b>	
Total Cost:					<b>\$</b>	<b>2600.00</b>				

Total Cost: \$ 2600.00

