

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 19805	Main Street: MORRISON_BV	Cross Street: SOUTH_PARK_DR	Location: NE
ADA ID: D4F7558D647F	Ramp Type: ParaDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 12.5	

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

RT RP < 5%

PROW/ADA:

R304.3.2

Street 1 Name **ROXBOROUGH RD**
 Stop Condition-Street 1 **Signal**
 Street 2 Name **MORRISON BV**
 Stop Condition-Street 2 **Signal**

Total Cost: \$ **3200.00**

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	68.0	N/A	Ramp Length RT (in)	92.5
Yes	Ramp Width LT (in)	64.0	Yes	Ramp Width RT (in)	64.0
No	Ramp Slope LT (%)	8.7	Yes	Ramp Slope RT (%)	2.6
Yes	Ramp XSlope LT (%)	0.5	Yes	Ramp XSlope RT (%)	0.9
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
	X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
N/A	X Walk 1 Width (in)	108.0	N/A	X Walk 2 Width (in)	110.0
	X Walk 1 Slope (%)	0.3		X Walk 2 Slope (%)	0.2
	X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	1.4
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes
	Road Slope (%)	1.5	N/A	Clear Space?	N/A
	Road X Slope (%)	1.3	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	7.0

