cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 13343 Main St	Main Street: E_INDEPENDENCE_BV				Location:	w		
			Cross Street: CHARLOTTETOWNE_AV					
ADA ID: D4FFE609D5C4 Ramp Type: Perp		Initial Pas	Initial Pass/Fail: Fail Overall Compliance: No				Severity Score:	10
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance						
	Possible Solutions:	Compliance Description Data			Compliance Description Da		Data	
	Remove & Replace Entire Ramp). N	I/A	Ramp Length (in)	94.5	Yes	Ramp Slope (%)	6.7
		N	lo	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	3.8
3/1/23/		N	/ A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
5-5-5	/	N	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		N	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A CONTRACT OF A		N	I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
6	Surveyor Notes:	N	I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	N	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
CONTRACTOR AND	2	N	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A LA LA		N	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		N	I/A	Shared Landing?	N/A			
	PROW/ADA:	N	I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1	N	/ A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	· ·	N	I/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	3			X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
	6	N	I/A	X Walk 1 Width (in)	111.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name CHARLOTTETOWNE AV				X Walk 1 Slope (%)	5.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 Signal				X Walk 1 X Slope (%)	5.6		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A		N	I/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		N	I/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

