cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

		•						
Intersection ID: 30544	Main Street: STONECROFT_PARK_DR		Cross Street: SUMMERHILL_RIDGE_DR				Location:	NW
ADA ID: D508D56017B4	56017B4 Ramp Type: PerpDiag			ail: Fail Overall O	o Severity Score:	10		
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description Data			Comp	Compliance Description	
Contral as a	Remove & Replace Curb Ram	p With	N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	5.1
	Two New Directional Ramps o	r	No	Ramp Width (in)	38.0	No	Ramp XSlope (%)	4.9
	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	3 5 5 11		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
the second secon	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
THE PROPERTY OF THE PROPERTY O	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
SUMMERHILL RIDGE DUS			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
5.			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A DE CONTRACTOR	6.		N/A	Shared Landing?	N/A			
And I Flack Marker	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
The state of the second	Not Found, R304.5.1, R304.5.	3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
These a filles				X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name SUMMERH	HILL RIDGE DR			X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	5.8
Stop Condition-Street 2	StopSign			X Walk 1 X Slope (%)	5.9		X Walk 2 X Slope (%)	0.8
Street 2 Name STONECR	ROFT PARK DR		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign			Road Slope (%)	3.8	N/A	Clear Space?	N/A
				Road X Slope (%)	4.6	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

