

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10040084 Main Street: TUCKASEEGEE\_RD Cross Street: N/A Location: S

ADA ID: D512F7D18884 Ramp Type: Directional1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 33.75

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name	TUCKASEEGEE RD
Stop Condition-Street 1	None
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Possible Solutions:	<u>C</u>
Remove & Replace Entire Ramp.	
	N
	N
	Ye
	N
	N
Surveyor Notes:	N
N/A	N
	N
	N
	N
PROW/ADA:	N
R304.5.1, R304.2.2	N
	N
	N
	N

Total Cost:		\$	1600.00

Comp	liance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	47.0	N/A	Grade	e Break?	N/A
No	Ramp Width (in)	47.5	N/A	Grade	e Break Slope (%)	0.0
No	Ramp Slope (%)	13.7	N/A	Grade	e Break XSlope (%)	0.0
Yes	Ramp XSlope (%)	1.4				
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	0.0
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	0.0	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	0.0	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	0.0	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	0.0	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset LT (in)	N/A
N/A	Shared Landing?	N/A	N/A	DWS	Offset RT (in)	N/A
N/A	Gutter Ponding?	0.0	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutte	er X Slope (%)	N/A
N/A	Painted X Walk1?	No		Road	Slope (%)	5.8
	X Walk 1 Direction	To N		Road	X Slope (%)	1.3
	X Walk 1 Width (in)	N/A		Clear	Space?	N/A
	X Walk 1 Slope (%)	5.8	N/A	Clear	Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	1.3	N/A	Storm	n Grate/Utility Hazard?	N/A
N/A	Ramp inside XWalk1?	N/A		Storm	n Grate/Utility Type	
N/A	Any Obstructions?	N/A				N/A
	Obstruction Type		Yes	Surfa	ce Condition? (G/P)	Good
		N/A	N/A	Curb	Slope (%)	14.





