

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10027514	Main Street: GRANDIN_RD	Cross Street: N/A	Location: S
ADA ID: D549E150726A	Ramp Type: BlendTrans1	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 22.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.		N/A	Ramp Length (in)	195.0
			Yes	Ramp Width (in)	119.0
			N/A	Flare Type LT	None
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			Yes	Landing Length (in)	90.0
			Yes	Landing Width (in)	109.0
			Yes	Landing Slope (%)	0.4
			Yes	Landing X Slope (%)	0.3
Surveyor Notes: NO CURB PROW/ADA: R304.5.3, R305, R302.7.2, R304.5.4			N/A	Flare Type RT	None
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			No	DWS Provided?	No
			N/A	DWS Contrast?	No
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	No
			N/A	DWS Offset (in)	N/A
			Yes	Gutter Ponding?	No
			No	Gutter Lip Ht (in)	0.5
Total Cost: \$ 3950.00			N/A	Painted X Walk1?	Yes
				X Walk 1 Direction	To NW
				X Walk 1 Width (in)	111.0
				X Walk 1 Slope (%)	6.5
				X Walk 1 X Slope (%)	2.1
			Yes	Ramp inside XWalk1?	Yes
				Road Slope (%)	2.1
				Road X Slope (%)	6.5
			Yes	Any Obstructions?	No
				Obstruction Type	
			N/A	Storm Grate/Utility Hazard?	No
				Storm Grate/Utility Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	N/A