

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 17613	Main Street: COLWICK_RD			Street:	GREENWICH_RD	Location:	SE		
ADA ID: D56E9E897AAD	Ramp Ty	Initial I	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data Complia			liance Description	Data	
		Remove & Replace Curb Ramp W	Vith	N/A	Ramp Length (in)	59.0	Yes	Ramp Slope (%)	7.0
		Two New Directional Ramps or		No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	6.1
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
TULION AND AND AND AND AND AND AND AND AND AN				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
GLEBAL		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
A C		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
5. S.				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	Mar Car			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
C C C C C C C C C C C C C C C C C C C		R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
				N/A	X Walk 1 Width (in)	101.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	GREENWICH RD	-			X Walk 1 Slope (%)	0.3		X Walk 2 Slope (%)	8.3
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	6.7		X Walk 2 X Slope (%)	0.8
Street 2 Name	COLWICK RD			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	5.0	N/A	Clear Space?	N/A
	- •				Road X Slope (%)	6.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

