

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13433Main Street:HAVENWOOD_RDCross Street:WOODLEAF_RDLocation:SWADA ID: D5AC6B87AFFCRamp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:50

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name HAVENWOOD RD
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2, R304.5.3

N/A
N/A
N/A
PROW/ADA:
Not Found, R304.2.2, R304.5.3
N/A
N/A
N/A
N/A

N/A

N/A

N/A

N/A

Field Measurements/Component Compilance					
Compliance Description			Compliance Description		Data
N/A	Ramp Length (in)	23.0	No	Ramp Slope (%)	13.5
Yes	Ramp Width (in)	50.0	No	Ramp XSlope (%)	10.5
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To E		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	8.9		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	7.3		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type		l	Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
-					





