

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



		. ,					
Intersection ID: 4744 Main Street: EDGEVALE_DR			et: TRINITY_RD		Location: SW		
ADA ID: D5EFAD08A339	Ramp Type: Combination1	Initial Pass	/Fail: Fail Overall C	ompliance: N	lo Severity Score:	22.5	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance				
	Possible Solutions:	Co	mpliance Description	Data Com	pliance Description	Data	
	Remove & Replace Entire Ramp	p. N/A	A Ramp Length LT (in)	62.5 N/A	Ramp Length RT (in)	44.0	
		No	Ramp Width LT (in)	41.0 No	Ramp Width RT (in)	44.0	
		No	Ramp Slope LT (%)	9.7 Yes	Ramp Slope RT (%)	5.8	
Alter Jat	0	No	Ramp XSlope LT (%)	2.7 No	Ramp XSlope RT (%)	2.2	
A DE DATE	T IT	N/A	A Ramp Length (in)	17.0 Yes	Ramp Slope (%)	7.0	
& TEILUN	Charles and the second	No	Ramp Width (in)	39.5 Yes	Ramp XSlope (%)	0.7	
	Surveyor Notes:	N/A	A Flare Type LT	N/A N/A	Flare Type RT	N/A	
E.	N/A	N/A	A Flare Slope LT (%)	N/A N/A	Flare Slope RT (%)	N/A	
		N/A	A Flare Traversable LT?	N/A N/A	Flare Traversable RT?	N/A	
		N/A	Landing Length (in)	N/A N/A	DWS Provided?	N/A	
		N/A	A Landing Width (in)	N/A N/A	DWS Contrast?	N/A	
	PROW/ADA:	N/A	Landing Slope (%)	N/A N/A	DWS Length (in)	N/A	
	R304.5.1, R304.5.1, R304.3.2,	N/A	A Landing X Slope (%)	N/A N/A	DWS Full Width?	N/A	
	R304.5.3	N/A		N/A N/A	DWS Offset (in)	N/A	
	I a state	N/A	A Shared Landing?	N/A			
	N/A	-	N/A N/A	Gutter Slope (%)	N/A		
Street 1 Name	None	N/A	Gutter Lip Ht (in)	N/A N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	TRINITY RD	N/A	A Painted X Walk1?	No N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A		X Walk 1 Direction	To N	X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A		X Walk 1 Width (in)	N/A	X Walk 2 Width (in)	N/A	
			X Walk 1 Slope (%)	2.2	X Walk 2 Slope (%)	N/A	
			X Walk 1 X Slope (%)	3.6	X Walk 2 X Slope (%)	N/A	
	Total Cost: \$	1800.00 N/A	A Ramp inside XWalk1?	N/A N/A	Ramp inside XWalk2?	N/A	
			Road Slope (%)	N/A	Clear Space?	N/A	
			Road X Slope (%)	N/A N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstruction?	N/A	
		1-			Obstruction Type		
						N/A	
				N/A	Storm Grate/Utility Hazard?	N/A	
					Storm Grate/Utility Type	10/5	
		1 3				N/A	

 Yes
 Surface Condition? (G/P)
 Good

 Curb Slope (%)
 3.2