

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

48.5

49.0

2.7

1.4

8.3

1.1

N/A

Good 11.6

Intersection ID: 10675 Main Street: HERRIN_AV Cross Street: THE_PLAZA Location: NW

ADA ID: D605B82072F6 Ramp Type: Combination1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
StopSign
Stop Condition-Street 1
HERRIN AV
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

RT RP < 5%

PROW/ADA:

Not Found, R304.5.1, R304.3.2

Total Cost: \$ 1800.00

Compliance Description Data Compliance Description Ramp Length LT (in) N/A Ramp Length RT (in) N/A 45.5 49.5 Yes Ramp Width LT (in) Yes Ramp Width RT (in) No Ramp Slope LT (%) 8.5 Yes Ramp Slope RT (%) Ramp XSlope LT (%) Yes Ramp XSlope RT (%) Yes 1.3 N/A Ramp Length (in) 36.0 Yes Ramp Slope (%) 42.0 Yes Ramp XSlope (%) No Ramp Width (in) N/A Flare Type LT N/A N/A Flare Type RT N/A N/A N/A Flare Slope LT (%) Flare Slope RT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A N/A Landing Width (in) **DWS Contrast?** N/A Landing Slope (%) N/A N/A DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A Painted X Walk2? N/A Painted X Walk1? No To SW X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in)

0.3

3.3

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Yes

X Walk 1 Slope (%) X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Any Obstruction?

Obstruction Type

Curb Slope (%)







N/A