cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14396	Main Street: BRIAR_CREEK_RD			Cross Street: COMMONWEALTH_AV				Location:	S
ADA ID: D61615673843	/3843 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance:			nce: N	o Severity Score:	26.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Read / 1 / 1 / 1		Possible Solutions:		Compliance Description D			ata Compliance Description		Data
		Remove & Replace Entire Ran	np.	N/A	Ramp Length (in)	27.0	No	Ramp Slope (%)	15.6
	121	-	•	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.6
	11.7			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
5 6	1 24			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	LITZE CONT			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	ALINEN	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
<u>हुन</u> हि	R AV	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
3/5/ 13				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	1 3 3 -			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	party to			N/A	Shared Landing?	N/A			
The star	F A Jan 1	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	110/41	Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
1 13 010	Andre Li			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
9 13 -	to all a little				X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
13A	A CONTRACT			N/A	X Walk 1 Width (in)	97.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	BRIAR CREEK RD				X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

