

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		`		• /					
Intersection ID: 45131	Cros	Cross Street: FOUR_SISTERS_LN				Location:	SE		
ADA ID: D62A04254B80	Ramp Ty	Ramp Type: Combination2			Initial Pass/Fail: Fail Overall Compliance: No				8.75
	Codes/Mitigation Info				Field Measure	ements/C	ompo	nent Compliance	
Possible Solutions:				Compliance Description Data Complian			liance Description	Data	
The second second		Remove & Replace Entire	Ramp.	N/A	Ramp Length LT (in)	44.5	N/A	Ramp Length RT (in)	52.0
				N/A	Ramp Width LT (in)	56.5	Yes	Ramp Width RT (in)	51.5
and the second	A CAR AND			N/A	Ramp Slope LT (%)	3.8	Yes	Ramp Slope RT (%)	5.4
	The state			N/A	Ramp XSlope LT (%)	0.1	Yes	Ramp XSlope RT (%)	1.1
PLASE	and the second			N/A	Ramp Length (in)	53.0	Yes	Ramp Slope (%)	3.4
R	D DAT			No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	1.0
	in the second	Surveyor Notes:		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	- States	LT RP < 5%		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	Sec. Sec.			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	Contraction of the second seco			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	1 million and a			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		PROW/ADA:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		Not Found, R304.5.1		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	AN A REAL TO	-		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	The rank (N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	StopSign			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	FOUR SISTERS LN			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A				X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	3.5		X Walk 2 Slope (%)	N/A
					X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	N/A
		Total Cost:	6 1600.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
					Road Slope (%)	N/A		Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			Anti-manufation of the Anti-				N/A	Any Obstruction?	N/A
		the second s							

Obstruction Type N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good Curb Slope (%)

16.4