


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10020012		Main Street: ARROWPOINT_BV		Cross Street: N/A		Location:		SE			
ADA ID: D68D3750642B		Ramp Type: Directional2		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 37.5			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance							
				Possible Solutions:		Compliance		Description		Data	
				Remove & Replace Entire Ramp.		N/A		Ramp Length (in)		80.0	
Surveyor Notes:				N/A		Yes		Ramp Width (in)		48.0	
						No		Ramp Slope (%)		14.3	
PROW/ADA:				R304.2.2, R304.5.3		No		Ramp XSlope (%)		6.0	
						N/A		Flare Type LT		N/A	
						N/A		Flare Slope LT (%)		N/A	
						N/A		Flare Traversable LT?		N/A	
						N/A		Landing Length (in)		0.0	
						N/A		Landing Width (in)		0.0	
						N/A		Landing Slope (%)		0.0	
						N/A		Landing X Slope (%)		0.0	
						N/A		Landing Curb? (Y/N)		N/A	
						N/A		Shared Landing?		N/A	
						N/A		Gutter Ponding?		0.0	
						N/A		Gutter Lip Ht (in)		0.0	
						N/A		Painted X Walk1?		No	
						N/A		X Walk 1 Direction		To N	
						N/A		X Walk 1 Width (in)		N/A	
						N/A		X Walk 1 Slope (%)		0.7	
						N/A		X Walk 1 X Slope (%)		11.6	
						N/A		Ramp inside XWalk1?		N/A	
						N/A		Any Obstructions?		N/A	
						N/A		Obstruction Type		Yes	
						N/A		Surface Condition? (G/P)		Good	
						N/A		Curb Slope (%)		3.1	
Street 1 Name		ENTRANCE									
Stop Condition-Street 1		StopSign									
Street 2 Name		N/A									
Stop Condition-Street 2		N/A									
Total Cost:		\$		1800.00							

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

R304.2.2, R304.5.3

Total Cost:

\$ 1800.00

