

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 2719 Main Street: BEAUVISTA DR Cross Street: FAIRVISTA_DR Location: NE ADA ID: D6C7E489A864 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 12.5

Codes/Mitigation Info/Possible Solution



HIGHLAND CREEK PY Street 1 Name Stop Condition-Street 2 None Street 2 Name **BEAUVISTA DR** Stop Condition-Street 1 StopSign

Possible Solutions: Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.2.2

Total Cost: 3200.00

Field Measurements/Component Compliance							
	Compliance Description		Data	Compliance Description		Description	Data
	N/A	Ramp Length (in)	57.0	No	Ramp	o Slope (%)	8.6
	Yes	Ramp Width (in)	48.0	Yes	Ramp	xSlope (%)	0.6
	N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	No
		X Walk 1 Direction	To W		X Wa	lk 2 Direction	To S
	N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	ılk 2 Width (in)	N/A
		X Walk 1 Slope (%)	4.5		X Wa	ılk 2 Slope (%)	0.9
		X Walk 1 X Slope (%)	1.2		X Wa	ılk 2 X Slope (%)	2.2
	N/A	Ramp inside XWalk1?	N/A	N/A	Ram	p inside XWalk2?	N/A
		Road Slope (%)	0.7	N/A	Clear	Space?	N/A
		Road X Slope (%)	1.6	N/A	Clear	Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
		Obstruction Type			Storn	n Grate/Utility Type	
			N/A				N/A
				Yes	Surfa	ice Condition? (G/P)	Good
	11/1						





