cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 46180	Main Street: SWEETSPIRE_RD			Cross Street: SEVEN_OAKS_DR				Location:	E	
ADA ID: D6E436D973EC	Ramp Ty	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance:			o Severity Score:	10	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	1. 1. 1.	Possible Solutions:		Compliance Description			Data Compliance Description			
		Remove & Replace Curb Ran	Ramp With	N/A	Ramp Length (in)	59.5	Yes	Ramp Slope (%)	5.2	
a table of a table	1. 1/1	Two New Directional Ramps	•	No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	2.8	
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
Contraction of the second	C3 ¹²¹			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	SEPT /			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
6		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	State (State 1)	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
the second secon	· · · · · · · · · · · · · · · · · · ·			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	A Calman /			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	N HOLER	2		N/A	Shared Landing?	N/A				
The second of the	THE REAL	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Sec. 11	1110/	Not Found, R304.5.1, R304.5.3	3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	5		•	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
		-			X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	SWEETSPIRE RD	_			X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	3.1	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.5		X Walk 2 X Slope (%)	1.3	
Street 2 Name	SEVEN OAKS DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	None				Road Slope (%)	3.3	N/A	Clear Space?	N/A	
					Road X Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P)

Good

