cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · · · · · · · · · · · · · · · · ·									
Intersection ID: 2580	tersection ID: 2580 Main Street: BENTGRASS_RUN_DR				GREAT_BEAR_CT	Location:	S		
ADA ID: D6F3600C649E	00C649E Ramp Type: PerpDiag			itial Pass/Fail: Pass Overall Compliance: N				o Severity Score:	22.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	6.4
		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.3
A CONTRACT		Equivalent. Remove & Replace Gutter.		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
Daniel A	RITIN ST			N/A	Flare Slope LT (%)	-	N/A	Flare Slope RT (%)	9.4
	193///			N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
A CARACTER AND A CARACTER				No	Landing Length (in)	42.5		DWS Provided?	No
		Surveyor Notes:		Yes	Landing Width (in)		N/A	DWS Contrast?	No
Taute to		N/A		Yes	Landing Slope (%)		N/A	DWS Length (in)	N/A
		N/A		Yes	Landing X Slope (%)		N/A	DWS Full Width?	No
- An			N/A	Landing Curb? (Y/N)		N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	No			100	
PROW/ADA: Not Found, R304.5.3, R304.2.1, R305, R302.7.2, R304.5.4				Yes	Gutter Ponding?		No	Gutter Slope (%)	5.8
				No	Gutter Lip Ht (in)	0.5		Gutter X Slope (%)	2.5
				N/A	Painted X Walk1?		N/A	Painted X Walk2?	2.5 No
				N/A	X Walk 1 Direction		N/A		NO To NW
						To NE		X Walk 2 Direction	-
		1		N/A	X Walk 1 Width (in)		N/A	X Walk 2 Width (in)	N/A
Street 1 Name	GREAT BEAR CT				X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	3.4
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	4.7		X Walk 2 X Slope (%)	0.1
Street 2 Name	BENTGRASS RUN DR			N/A	Ramp inside XWalk1?	N/A		Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	1.2	N/A	Clear Space?	Yes
					Road X Slope (%)	2.8	N/A	Clear Space to XWalk (in)	N/A
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost: \$	3950.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
4									

es Surface Condition? (G/P) Good

