

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 19600 Main Street: SCOFIELD_RD **Cross Street: WINTERCREST_LN** Location: **Overall Compliance: No** Severity Score: 13.75 ADA ID: D7042FA1500D Ramp Type: Directional1 Initial Pass/Fail: Fail

Codes/Mitigation Info/Possible Solution



Street 1 Name	SCOFIELD RD
Stop Condition-Street 1	StopSign
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Possible Solutions:	9
Remove & Replace Entire Ramp.	
·	١
	Y
	N
	1
	N
Surveyor Notes:	N
N/A	1
	N
	1
	1
PROW/ADA:	1
R304.5.3	N
	1
	ı
	N

Total Cost:	\$	1600.00
10101 0001.	•	1000.00

Field Measurements/Component Compliance							
Compl	iance Description	Data	Comp	liance Description	Data		
N/A	Ramp Length (in)	232.0	N/A	Grade Break?	N/A		
Yes	Ramp Width (in)	58.5	N/A	Grade Break Slope (%)	0.0		
Yes	Ramp Slope (%)	11.8	N/A	Grade Break XSlope (%)	0.0		
No	Ramp XSlope (%)	3.7					
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A		
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A		
N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No		Road Slope (%)	4.6		
	X Walk 1 Direction	To S		Road X Slope (%)	5.2		
	X Walk 1 Width (in)	N/A		Clear Space?	N/A		
	X Walk 1 Slope (%)	4.6	N/A	Clear Space to XWalk (in)	N/A		
	X Walk 1 X Slope (%)	5.2	N/A	Storm Grate/Utility Hazard?	N/A		
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type			
N/A	Any Obstructions?	N/A			N/A		
	Obstruction Type		Yes	Surface Condition? (G/P)	Good		
		N/A	N/A	Curb Slope (%)	12.0		





