

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 9841	Main Street: N_GRAHAM_ST			Cross Street: WOODWARD_AV					Location:	NE
ADA ID: D71E3A116B55	Ramp Type: Perp			Initial Pass/Fail: Pass Overall Compliance: Yes					es Severity Score:	0
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
Possible Solutions:									liance Description	Data
· · · · · · · · · · · · · · · · · · ·	A SELE	N/A			N/A	Ramp Length (in)	79.0		Ramp Slope (%)	6.4
	1 / AGA / F.S.				Yes	Ramp Width (in)	60.0		Ramp XSlope (%)	1.4
	Contract				N/A	Flare Type LT	Sloped		Flare Type RT	N/A
					N/A	Flare Slope LT (%)	•	N/A	Flare Slope RT (%)	1.7
					N/A	Flare Traversable LT?		N/A	Flare Traversable RT?	No
					Yes	Landing Length (in)	60.0		DWS Provided?	Yes
		Surveyor Notes:			Yes	Landing Width (in)		Yes	DWS Contrast?	Yes
		N/A			Yes	Landing Slope (%)	1.7	Yes	DWS Length (in)	24.0
					Yes	Landing X Slope (%)	1.3	Yes	DWS Full Width?	Yes
& 8				N/A	Landing Curb? (Y/N)	No		DWS Offset (in)	0.0	
A SAL A BOOM TO THE					N/A	Shared Landing?	No			
PROW/ADA:					Yes	Gutter Ponding?	No		Gutter Slope (%)	0.6
	N/A			Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.4	
Street 1 Name N GRAHAM ST					N/A	Painted X Walk1?		N/A	Painted X Walk2?	N/A
						X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	5.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal					X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A		Clear Space?	Yes
	1071					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					Yes	Any Obstructions?	No		Storm Grate/Utility Hazard?	No
		Total Cost:	\$	0.00		Obstruction Type			Storm Grate/Utility Type	
			Ŷ	0.00			N/A			N/A
							IN/A			IN/A

