

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 274	tersection ID: 27422 Main Street: BALLANTYNE_COMMONS_PY Cross Street: STONEBRIAR_DR							Location:	NW
ADA ID: D74047CB	D74047CB2644 Ramp Type: Perp				Initial Pass/Fail: Fail Overall Compliance: No				46.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Carl C and	Cart is	Possible Solutions:		Compliance Description		Data Compliance Description			Data
E ENSI		Remove & Replace Entire Ram	ıp.	N/A	Ramp Length (in)	106.5	No	Ramp Slope (%)	8.9
As a company			•	No	Ramp Width (in)	37.0	No	Ramp XSlope (%)	7.1
BT V				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
F A	And I - Shake			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	and a second sec			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Contraction and the				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
the second second		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
BALLANTYNE COL				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		~		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
Martin Colones in the attended	(03)	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
A A MARK	the the the termination of terminatio of termination of	Not Found, R304.5.1, R304.2.2, R304.5.3	2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Same and the second			-,	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		4			X Walk 1 Direction	To S		X Walk 2 Direction	N/A
AND LANGE				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name BALLANTYNE COMMONS PY					X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	4.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							Yes	Surface Condition? (G/P)	Good





