cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		(-			/					
Intersection ID: 11263	rsection ID: 11263 Main Street: W_TRADE_ST		Cross	Cross Street: S_SYCAMORE_ST				Location:	NE	
ADA ID: D749A584C7C3	Ramp Ty	mp Type: Combination1			Initial Pass/Fail: Fail Overall Complian			nce: N	o Severity Score:	10
Codes/Mi	tigation Info/	Possible Solution				Field Measu	rements/C	ompo	nent Compliance	
X X YOU Y	Nº SALAN MONT	Possible Solutions:			Compl	iance Description			liance Description	Data
San Pro 198	aller .	Remove & Replace Entire	Ran	np.	N/A	Ramp Length LT (in)	72.0	N/A	Ramp Length RT (in)	80.0
					Yes	Ramp Width LT (in)	48.0	No	Ramp Width RT (in)	44.0
a service a film	· - h. h.				Yes	Ramp Slope LT (%)	1.3	Yes	Ramp Slope RT (%)	6.2
	A The State				Yes	Ramp XSlope LT (%)	1.7	Yes	Ramp XSlope RT (%)	1.9
					N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	4.1
					Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	2.3
		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
- E	and Harton	LIGHT RAIL CONSTRUCT			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	they to the state	ACROSS W TRADE ST			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
STRADE ST	Nur as				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
6	C C C				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
a de la companya de l		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
CARLE SALE		Not Found, R304.5.1			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	NO W OF	·			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	AT A				N/A	Shared Landing?	N/A			
AR ALS A PRIMI					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	W TRADE ST				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A					X Walk 1 Direction	To S		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	3.0		X Walk 2 Slope (%)	N/A
						X Walk 1 X Slope (%)	3.1		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A		Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			*					N/A	Any Obstruction?	N/A
				1. 24					Obstruction Type	N/A

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A

Yes	Surface Condition? (G/P)	Good
	Curb Slope (%)	27.7





