

Access Compliance Report

Public Rights-of-Way (Curb Ramps)

Intersection ID: 6462	Main Street: BURGANDY_DR	Cross Street: MINERAL_SPRINGS_RD	Location:	E
ADA ID: D7864B9F28F8	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 5
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance		



Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.2.3

Total Cost: \$ 1600.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	26.5	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	58.0	Yes	Grade Break Slope (%)	3.5
Yes	Ramp Slope (%)	4.7	Yes	Grade Break XSlope (%)	0.8
Yes	Ramp XSlope (%)	0.0			
Yes	Flare Type LT	N/A	No	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
No	Landing Length (in)	58.5	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	55.0	Yes	DWS Contrast?	Yes
No	Landing Slope (%)	4.6	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	0.9	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	Yes	Yes	DWS Offset LT (in)	20.0
N/A	Shared Landing?	No	Yes	DWS Offset RT (in)	1.0
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.4
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.4
N/A	Painted X Walk1?	Yes		Road Slope (%)	3.8
	X Walk 1 Direction	To NE		Road X Slope (%)	2.8
	X Walk 1 Width (in)	112.0		Clear Space?	Yes
	X Walk 1 Slope (%)	3.8	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	2.8	Yes	Storm Grate/Utility Hazard?	No
Yes	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	5.4

