


Access Compliance Report

Public Rights-of-Way (Curb Ramps)

Intersection ID: 25688	Main Street: PLANTERS RIDGE RD	Cross Street: PROVIDENCE TRAIL LN	Location:	N
ADA ID: D7CC246725E1	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 47.5

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	95.0	No	Ramp Slope (%)	9.8
			No	Ramp Width (in)	24.0	Yes	Ramp XSlope (%)	1.4
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Surveyor Notes:		N/A	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
PROW/ADA:		Not Found, R304.5.1, R304.2.2	N/A	Shared Landing?	N/A	N/A	Gutter Slope (%)	N/A
			N/A	Gutter Ponding?	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A	Painted X Walk2?	N/A
			N/A	Painted X Walk1?	No	N/A	X Walk 2 Direction	N/A
				X Walk 1 Direction	To SE		X Walk 2 Width (in)	N/A
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Slope (%)	N/A
				X Walk 1 Slope (%)	3.1		X Walk 2 X Slope (%)	N/A
				X Walk 1 X Slope (%)	3.6		Ramp inside XWalk2?	N/A
			N/A	Ramp inside XWalk1?	N/A	N/A	Clear Space?	N/A
				Road Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				Road X Slope (%)	N/A	N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Type	
				Obstruction Type				N/A
						N/A		
						Yes	Surface Condition? (G/P)	Good

