

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 50304 Main Street: PINE\_TERRACE\_CT Cross Street: S\_J\_LAWRENCE\_RD Location: NW **Severity Score:** ADA ID: D7DEF59299B3 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** 8.75

Codes/Mitigation Info/Possible Solution



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1

**PINE TERRACE CT** StopSign **S J LAWRENCE RD** None

Possible Solution				
Possible Solutions:	Co			
Remove & Replace Curb Ramp With Two New Directional Ramps or				
	N/A			
	N/A			
	N/A			
Surveyor Notes:	N/A			
N/A	N/A			
	N/A			
	N/A			
	N/A			
PROW/ADA:				
Not Found, R304.5.1	N/A			
,				
	N/A			
	N/A			

Total Cost: 3200.00

Field Measurements/Component Compliance								
	Compliance Description		tion Data Compliance Description		liance Description	Data		
	N/A	Ramp Length (in)	49.0	Yes	Ramp Slope (%)	5.2		
	No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	0.4		
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
	N/A	Shared Landing?	N/A					
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No		
		X Walk 1 Direction	To S		X Walk 2 Direction	То Е		
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
		X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	0.6		
		X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	2.1		
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
		Road Slope (%)	1.0	N/A	Clear Space?	N/A		
		Road X Slope (%)	0.4	N/A	Clear Space to XWalk (in)	N/A		
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
		Obstruction Type			Storm Grate/Utility Type			
			N/A			N/A		
				Yes	Surface Condition? (G/P)	Good		
T 20								





