cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Curb Slope (%)

3.9

| | | • | | | / | | | | | | |
|---|-------------------------------|---|--------------------|--------------|--|-----------------------|-------|-----------------------------|-----------------------------|-------|--|
| Intersection ID: 24374 | Main Street: BEVERLY_CREST_BV | | | | Cross Street: HUGH_FOREST_RD | | | | Location: S | | |
| ADA ID: D81BA64CF1E3 | Ramp Type: Co | Ramp Type: Combination1Diag | | | nitial Pass/Fail: Fail Overall Complia | | | nce: No Severity Score: 0 | | 0 | |
| Codes | | Field Measurements/Component Compliance | | | | | | | | | |
| the second se | Possible | Possible Solutions: | | | Compliance Description Data | | | Compliance Description Data | | | |
| The second | Remo | ove & Replace Curb | Ramp W | /ith | N/A | Ramp Length LT (in) | 39.0 | N/A | Ramp Length RT (in) | 40.0 | |
| E | | New Directional Ram | | - | Yes | Ramp Width LT (in) | 48.0 | Yes | Ramp Width RT (in) | 48.0 | |
| | Equiv | /alent. | | | Yes | Ramp Slope LT (%) | 7.2 | Yes | Ramp Slope RT (%) | 0.1 | |
| | L. | | | | Yes | Ramp XSlope LT (%) | 1.8 | Yes | Ramp XSlope RT (%) | 1.5 | |
| 20230 | | | | | N/A | Ramp Length (in) | 24.0 | No | Ramp Slope (%) | 9.8 | |
| THE A | - And the | | | | No | Ramp Width (in) | 46.5 | Yes | Ramp XSlope (%) | 2.0 | |
| The second se | Surveyor | r Notes: | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| B | RT RI | P < 5% | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| | 5 | | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| | | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | |
| | | | | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| | PROW/A | ADA: | | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| 110 m | R304 | l.5.1, R304.2.2 | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| | | | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| and a star a starting of the | 1 188 | | | | N/A | Shared Landing? | N/A | | | | |
| | | | | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| Street 1 Name | Signal | | | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| Stop Condition-Street 1 HI | UGH FOREST RD | | | | N/A | Painted X Walk1? | Yes | N/A | Painted X Walk2? | Yes | |
| Street 2 Name | Signal | | | | | X Walk 1 Direction | To NE | | X Walk 2 Direction | To NW | |
| Stop Condition-Street 2 PINEVILL | E MATHEWS DR | | | | | X Walk 1 Width (in) | 112.0 | | X Walk 2 Width (in) | 119.0 | |
| | | | | | | X Walk 1 Slope (%) | 0.6 | | X Walk 2 Slope (%) | 1.7 | |
| | | | | | | X Walk 1 X Slope (%) | 4.0 | | X Walk 2 X Slope (%) | 2.2 | |
| | Total Cos | st: | \$ 32 | 00.00 | N/A | Ramp inside XWalk1? | Yes | N/A | Ramp inside XWalk2? | Yes | |
| | | | | | | Road Slope (%) | 2.2 | | Clear Space? | N/A | |
| | | | | | | Road X Slope (%) | 0.0 | N/A | Clear Space to XWalk (in) | N/A | |
| | | DI DE AS | | S. S. Sector | 1 a beiling | | | N/A | Any Obstruction? | N/A | |
| | | | | | | | | | Obstruction Type | | |
| | | | | | | A LOUGH | | | | N/A | |
| | | | | | | | | N/A | Storm Grate/Utility Hazard? | N/A | |
| | | | | | | | | | Storm Grate/Utility Type | | |
| | | | Contraction of the | | - | | | | | N/A | |
| | | | | 1 | | | | Yes | Surface Condition? (G/P) | Good | |