

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 46785 Main Street: DOMINION\_VILLAGE\_DR **Cross Street: AUTUMN HARVEST LN** Location: N Severity Score: **ADA ID: D83A0CEA7380** Ramp Type: BlendTrans1 Initial Pass/Fail: Fail **Overall Compliance: No** 8.75

**Codes/Mitigation Info/Possible Solution** 



**DOMINION VILLAGE DR** Street 1 Name Stop Condition-Street 1 None Street 2 Name N/A Stop Condition-Street 2 N/A Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1

	Total Cost:			
101	131			



3200.00

Field Measurements/Component Compliance						
Compl	liance Description	Data	Comp	liance Description	Data	
N/A	Ramp Length (in)	47.5	Yes	BlendTrans Slope (%)	2.6	
No	Ramp Width (in)	47.0	Yes	BlendTrans XSlope (%)	0.0	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A	
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	0.3		Clear Space?	N/A	
	Road X Slope (%)	2.7	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A	l		N/A	
			Yes	Surface Condition? (G/P)	Good	
	and the same of th		No	Curb Slope (%)	19.0	