

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27019 Main Street: ENDHAVEN\_LN Cross Street: ROUGEMONT\_LN Location: NE

ADA ID: D88CD17CAC56 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

ROUGEMONT LN StopSign ENDHAVEN LN None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Total Cost: \$ 3200.00

Field Measurements/Component Compliance						
	Compl	iance Description	Data	Compli	ance Description	Data
	N/A	Ramp Length (in)	72.0	Yes	Ramp Slope (%)	6.0
	No	Ramp Width (in)	46.0	No	Ramp XSlope (%)	5.5
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	N/A	Shared Landing?	N/A			
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	7.3
		X Walk 1 X Slope (%)	5.9		X Walk 2 X Slope (%)	2.5
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	4.7	N/A	Clear Space?	N/A
		Road X Slope (%)	5.5	N/A	Clear Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type		l	Storm Grate/Utility Type	
			N/A	l		N/A
				Yes	Surface Condition? (G/P)	Good
	Moto	* 600		-		





