

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

51.0

60.5

6.1

1.5

5.1

0.2

N/A

N/A N/A

N/A

N/A

Intersection ID: 51470 Main Street: HUCKS LANDING DR Cross Street: HUCKS RD Location: **Overall Compliance: No** ADA ID: D8D87F3ABAC5 Ramp Type: Combination1 Initial Pass/Fail: Fail Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

Yes

Yes

Yes

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Flare Traversable RT?

Ramp XSlope RT (%)

Data

56.0

58.0

9.7

1.9

48.0

47.5

N/A

No

N/A

4.4

0.7

N/A

To SW



Street 1 Name None Stop Condition-Street 1 **HUCKS RD** N/A Street 2 Name Stop Condition-Street 2 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.3.2

Total Cost:



N/A

Ramp inside XWalk1?



1800.00

Road Slope (%) N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good Curb Slope (%) 14.7



