cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10026761 Main Street: FOLGER DR Cross Street: N/A Location: NE									
Intersection ID: 10026761	ection ID: 10026761 Main Street: FOLGER_DR			Cross Street: N/A					NE
ADA ID: D8E7A3BEAEFF Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No					o Severity Score:	26.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
		Remove & Replace Curb Ramp W	/ith	N/A	Ramp Length (in)	71.5	No	Ramp Slope (%)	12.8
		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.9
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	1			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	As a second	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second second	11 C 12 1	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A CONTRACT OF A CONTRACT.				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the second se				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
the second		·····		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SW		X Walk 2 Direction	To S
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE	-			X Walk 1 Slope (%)	3.3		X Walk 2 Slope (%)	5.7
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	4.0		X Walk 2 X Slope (%)	2.1
Street 2 Name	FOLGER DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	1.8	N/A	Clear Space?	N/A
					Road X Slope (%)	4.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

