

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15124Main Street: CHEROKEE_RDCross Street: S_LAUREL_AVLocation:EADA ID: D8F98F9BB4F7Ramp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW	
Street 1 Name	CHEROKEE RD
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:	Co
Remove & Replace Entire Ramp.	N/A
·	Ye
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
Not Found, R304.2.2	N/A
·	N/A
	N/A
	N//



Total Cost:



1850.00

Field Measurements/Component Compliance									
Comp	liance Description	Data	Compl	iance	Description	Data			
N/A	Ramp Length (in)	96.0	No	Ramp	Slope (%)	10.2			
Yes	Ramp Width (in)	58.0	Yes	Ramp	XSlope (%)	0.2			
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A			
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A			
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A			
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A			
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A			
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A			
N/A	Shared Landing?	N/A							
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A			
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A			
	X Walk 1 Direction	To S		X Wa	lk 2 Direction	N/A			
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A			
	X Walk 1 Slope (%)	7.2		X Wa	lk 2 Slope (%)	N/A			
	X Walk 1 X Slope (%)	3.4		X Wa	lk 2 X Slope (%)	N/A			
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A			
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A			
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A			
N/A	Any Obstructions?	N/A	N/A	Storm	n Grate/Utility Hazard?	N/A			
	Obstruction Type			Storm	n Grate/Utility Type				
		N/A				N/A			
			Yes	Surfa	ce Condition? (G/P)	Good			